



Restrictions within CE Marking Regarding Third-Party Neck support

The restrictions specified below apply to the use of third-party neck support while maintaining the CE marking on the following product series from Mercado Medic AB; REAL 9000 PLUS, REAL 6100 PLUS and REAL 6100 PLUS LiNX.

The headrest must be mounted on Mercado Medic's high backrest or on the high Slingback backrest mechanism. When ordering a high backrest with hole pattern compatibility for Anatomic Sitt neck supports, you need to specify the desired size and configuration of the backrest.

Additionally, complete the order with Article 805753 to ensure the backrest plate is delivered with a complete hole pattern.

If a different placement of the hole pattern is required (than the default described below), this must be specified in the order.

805753 Hole Pattern: M5 55x65, 40 mm from the upper edge of the backrest unless otherwise specified, mounting plate excluded

For Slingback backrests measuring 40 cm in height, the neck support mount is attached to the upper crossbar using a clamp connection.

805665 Headrest bracket for Slingback-backrest for Anatomic-SITT headrest, mounting plate excluded

If the above criteria are met, the CE marking can be maintained on the product. This means that the product can be restored to its original condition without requiring Mercado Medic's approval.

However, the product still has a maximum expected service life of 10 years, after which it requires an inspection according to chapter 6.3 in the Instructions for use for the above-mentioned products.